

# UP-FRONT IDENTIFICATION OF VALIDATION CANDIDATE SOURCE

FTSCPAC  
CDR CAROL MARCINEK

CDM-ISEA WORKING GROUP  
VALIDATIONS SUB-GROUP  
24-26 OCT 00

# VALIDATION CANDIDATES

Caveat:

- Only looked at candidates that are loaded into TOMCAT for CILS-TAT availabilities

# VALIDATION CANDIDATES

- SVT
  - ESWBSs 43611L\* (Alarm Safety and Warning Systems), 49111\* (Test Equipment), and 76111\* (Small Arms and Pyrotechnics Launching Devices)
  - Source Code “G”/“J” RIC match
- LMS
  - SCWA
  - Other SSVA elements

# USS LAKE CHAMPLAIN (CG 57)

- TAT ship, currently in avail (09-06-00 – 11-08-00)
- SVT had 4,308 validation candidates (757 ESWBS and 3,551 G/J)
- Total number of transactions created: 7,473
  - 560 adds, 533 deletes, and 6,380 changes
- Number of transactions from initial 4,308
  - 93 adds, 130 deletes, and 2,456 changes

# USS LAKE CHAMPLAIN (CG 57)

(Cont'd)

- Above and Beyond Transactions:
  - 467 adds, 403 deletes, and 3,924 changes
- Total Data Elements Corrected:
  - 650 Parent EINs, 1,218 Parent S/Ns, 1,368 Workcenters, 506 PRIDs, 1,053 EFDs, 2,564 S/Ns, 349 Locations, 1,077 EINs, and 1 ISC
- ROI
  - With going-in candidates, 5.2%
  - With benefit of SVT experience, 25.4%

# USS RENTZ (FFG 46)

- TAT ship, currently in avail (08-30-00  
- 11-01-00)
- SVT had 3,454 validation candidates (681 ESWBS and 2,773 G/J)
- Total number of transactions created:  
3,532
  - 459 adds, 409 deletes, and 2,664 changes
- Number of transactions from initial 3,454
  - 221 adds, 322 deletes, and 1,426 changes

# USS RENTZ (FFG 46)

## (Cont'd)

- Above and Beyond Transactions:
  - 238 adds, 87 deletes, and 1,238 changes
- Total Data Elements Corrected:
  - 187 Parent EINs, 330 Parent S/Ns, 265 Workcenters, 230 PRIDs, 730 EFDs, 1,057 S/Ns, 280 Locations, 366 EINs
- ROI
  - With going-in candidates, 15.7%
  - With benefit of SVT experience, 25.1%

# TAKE-AWAYS

- SVT experience improves ROI from initial candidate selection
- Until up-front installation/logistics delivery process is improved, will need to keep validators correcting ship's configuration